



SKODA OCTAVIA COMBI: BB8968

Vinnumber:	TMBJG7NE8F0170497	Versionname:	1.6 CRTDI 77KW GREENTEC AMBITION
First Registrationdate:	16/02/2015	Fiscalpower:	
Expertise Mileage:	174469	Power Kw:	77
Bodytype:	Break	Body color:	Light Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3828
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunction	Type of Tow bar
Seats F heated	Tow bar fixed
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection


Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear

	205/55/16/91 H Steel			
Winter tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

	Compressor	Yes
Total cost ex VAT		1185,56
Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)		308,20



Windscreen, Stone chip(s), Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bodywork, Not original part, Acceptable 0,00

No pictures to display