



OPEL Astra: 1CBI345			
Vinnnumber:	<b>WOLPE8EF0C8014268</b>	Versionname:	<b>ASTRA BRE Cosmo FAP 125PK</b>
First Registrationdate:	<b>11/10/2011</b>	Fiscalpower:	
Expertise Mileage:	<b>191119</b>	Power Kw:	<b>92</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>MOET GEDAAN WORDEN</b>	Parking lot:	<b>3826</b>
Maintenance:	<b>NOT OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	<b>SD</b> Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining semi-artificial leather</b>
Type of climate control:	<b>Autom climate control</b>

Limited Technical Inspection			
Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

Degree of wear				
	<b>225/50/17/98 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Fulda: 4 mm</b>	Fr.R.	<b>Fulda: 4 mm</b>
	Re.L.	<b>Uniroyal: 9 mm</b>	Re.R.	<b>Uniroyal: 9 mm</b>

Assistance equipment	
Repair kit	<b>Yes</b>
Compressor	<b>Yes</b>
Total cost ex VAT	<b>512,80</b>
Door R R, Bump(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Ignition key, Damaged, P - Check	<b>0,00</b>



Wing F L, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

<i>No pictures to display</i>	
Wing R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), LI - Repair and paint (complete)	259,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Maintenance, Maintenance, Execute	0,00
-----------------------------------	------



Floor covering F L, Hole, Acceptable	0,00
--------------------------------------	------

<i>No pictures to display</i>	
Door R R, Bump(s), PDR - Knock out without painting	63,00



Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), Acceptable	0,00

<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Seat cover F L, Worn, P - Check	0,00
---------------------------------	------



Roof, Stone chip(s), Acceptable	0,00
---------------------------------	------

<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00

Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	