



VOLVO V60: 1EFJ121			
Vinnumber:	YV1FW84A1D1116625	Versionname:	V60 D2 Base St/St 115PK
First Registrationdate:	15/11/2012	Fiscalpower:	
Expertise Mileage:	176915	Power Kw:	84
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	UITVOEREN	Parking lot:	2230
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS portable		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1473,35
Daytime running lights L, Damaged, E - Replace			131,44



Bonnet, Scratch(es), LI - Repair and paint (complete)	0,00
---	-------------



Internal Boot Lining L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel F L, Damaged, Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear bulkhead lining, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Internal Boot Lining R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	235,80
<i>No pictures to display</i>	
Door panel F R, Damaged, Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Stone chip(s), Windscreen repair	0,00



Maintenance, Maintenance, Execute	0,00
-----------------------------------	------



Bumper grille F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door frame F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	462,35



Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Repaired, P - Check	0,00



Tires, Not original part, P - Check	0,00
-------------------------------------	------



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bump(s), PDR - Knock out without painting 142,20



Door panel R R, Damaged, E - Replace 114,00



Front bumper, Damaged, Le - Replace and paint 0,00



Door panel R L, Damaged, E - Replace 114,00



Door frame R L, Damaged, Acceptable 0,00

No pictures to display

Wing R R, Bump(s), PDR - Knock out without painting 63,00



Outer door handle F L, Scratch(es), Paint 115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display