



TOYOTA Avensis: 1GXX957			
Vinnumber:	<b>SB1ED76L20E130244</b>	Versionname:	<b>DIESEL</b>
First Registrationdate:	<b>27/05/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>71156</b>	Power Kw:	<b>91</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3303</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options			
Radio CD		Seats electric F L	
GPS storage		Central consol F	
GPS storage	<b>HD</b>	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar removable</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		

Limited Technical Inspection			
Power steering	<b>Yes</b>	Battery functioning	<b>Yes</b>
Airco functioning	<b>OK</b>	Sound engine	<b>OK</b>
Tires wear profile	<b>OK</b>	Clutch test	<b>OK</b>
Idle position	<b>OK</b>	Wiper fluid level	<b>OK</b>
Engine startingtime	<b>OK</b>	Lighting	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiperblades	<b>OK</b>
Transmission	<b>OK</b>		
Handbrake	<b>OK</b>		

Degree of wear				
	<b>215/55/17/98 V LightMetal</b>			
Winter tyres:	Fr.L.	<b>Fulda: 7 mm</b>	Fr.R.	<b>Fulda: 7 mm</b>
	Re.L.	<b>Fulda: 5 mm</b>	Re.R.	<b>Fulda: 4,5 mm</b>

Assistance equipment			
Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>468,39</b>
Door R L, Bump(s), Acceptable			<b>0,00</b>



Bumper moulding F R, Scratch(es), E - Replace	<b>14,40</b>
---	--------------



Seat cover R, Stain, Cleaning 25,00



Bumper R, Scratch(es), Acceptable 0,00



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Dashboard, Scratch(es), Smart repair 110,64



Wing R L, Bump(s), Acceptable 0,00



Alloy rim F L polished, Scratch(es), Acceptable 0,00

