


BMW 1: 1GKG757

Vinnumber:	WBA1C91010J521623	Versionname:	1 HATCH 116d Eff.Dyn.Ed. 116PK
First Registrationdate:	3/03/2014	Fiscalpower:	
Expertise Mileage:	116140	Power Kw:	85
Bodytype:	Hatchback	Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4816
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 T Steel			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Semperit: 6 mm	Re.R.	Semperit: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

 Total cost ex VAT 2627,40

 Door panel R R, Damaged, Smart repair 110,64

 Wheel cover R R, Scratch(es), E - Replace 30,00



Door R L, Bad repair, Paint 0,00



Wing R R, Chemical polution, LI - Repair and paint (complete) 308,20



Wheel cover F R, Scratch(es), E - Replace 30,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80




Door F L, Bad repair, Paint 0,00




Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20





Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Bad repair, Acceptable 0,00

No pictures to display

Backrest cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Wheel cover R L, Scratch(es), E - Replace 30,00



Wing R L, Bad repair, Paint 0,00




Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 370,00



Seat cover F R, Stain, Cleaning 25,00



Wing F R, Chemical polution, LI - Repair and paint (complete) 220,18

