



BMW 3: 1BIZ668

Vinnumber:	WBAUY11040F046732	Versionname:	3 TOURING 320d 163PK
First Registrationdate:	10/06/2011	Fiscalpower:	
Expertise Mileage:	172493	Power Kw:	120
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3513
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Semperit: 7 mm	Fr.R.	Semperit: 7 mm
	Re.L.	Semperit: 5 mm	Re.R.	Semperit: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2341,21
-------------------	----------------

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56
--	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------






Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Sill outer R, Broken, Le - Replace and paint 0,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Stain, Cleaning 100,00



Door R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display


Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Sill outer L, Scratch(es), It - Spot repair 115,56




Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Door F R, Bump(s), LI - Repair and paint (complete) 414,35

