


BMW 3: 1GIF929

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------|
| Vinnumber: | WBA3D11080J626361 | Versionname: | 3 BER 318d 136PK |
| First Registrationdate: | 14/02/2014 | Fiscalpower: | |
| Expertise Mileage: | 113532 | Power Kw: | 100 |
| Bodytype: | Berline | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | 1/02/2018 | Parking lot: | 3608 |
| Maintenance: | NOT OK | | |
| Battery functioning: | Yes | | |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|----------------------|
| Radio CD | | Central consol F | |
| GPS storage | | Front parking sensors | |
| GPS storage | HD | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | Tow bar fixed |
| Windows electric R | | | |
| Cruise Control | | | |
| Steering wheel multifunctional | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 205/60/16/96 H LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Continental: 8 mm | Re.R. | Continental: 8 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 668,64 |
|-------------------|--------|

| | |
|-------------------------------------|------|
| Door panel F R, Damaged, Acceptable | 0,00 |
|-------------------------------------|------|



| | |
|--|-------|
| Floor covering F L, Burned, Smart repair | 64,32 |
|--|-------|



Door panel F L, Damaged, Acceptable 0,00



Wing F L, Difference in color, Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (partial) 220,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Worn, Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), I - Repair 50,00



Bonnet, Chemical polution, Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), I - Repair 50,00



Fuel cap cover, Damaged, Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00

No pictures to display

Ceiling, Burned, Smart repair 64,32



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (partial) 220,00

