




BMW 5: 1GNF878			
Vinnnumber:	WBA5J11010D335958	Versionname:	5 TOURING 518d 136PK
First Registrationdate:	17/03/2014	Fiscalpower:	
Expertise Mileage:	77735	Power Kw:	100
Bodytype:	Break	Body color	Silver
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2713
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		
Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK
Degree of wear			
Winter tyres:	225/55/17/101 V LightMetal		
	Fr.L.	Michelin: 5 mm	Fr.R.
	Re.L.	Michelin: 5 mm	Re.R.
		Michelin: 5 mm	Michelin: 5 mm
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			793,32
Wing F L, Bad repair, Paint			0,00
			
			
Wing R R, Bump(s), Acceptable			0,00
No pictures to display			
Door F L, Bad repair, Paint			0,00

 		Rearview mirror L complete, Scratch(es), Acceptable	0,00
No pictures to display		Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
 		Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
 		Alloy rim F L, Scratch(es), Acceptable	0,00
No pictures to display		Roof pillar L, Bad repair, Paint	0,00
  		Door R L, Bad repair, Paint	0,00
 		Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
 		Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
 		Wing R L, Bad repair, Paint	0,00
  		Backrest cover F L, Worn, Acceptable	0,00
 		Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16

