



FORD S Max: 1EXM127

Vinnnumber:	WF0SXXGBWSDJ88498	Versionname:	S-MAX Econetic Titanium
First Registrationdate:	15/04/2013	Fiscalpower:	St&St DPF 115PK
Expertise Mileage:	148281	Power Kw:	85
Bodytype:	MPV	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3629
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Seats electric F L
GPS storage	Seats electric F R
GPS storage	HD Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			830,23
Door F R, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Front bumper, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)			264,21



Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		

No pictures to display	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Windscreen, Damaged, E - Replace	0,00
	
Wing R R, Bump(s), Acceptable	0,00
No pictures to display	
Door R R, Bump(s), LI - Repair and paint (complete)	382,02
	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Protection plate M, Tear, E - Replace	89,00
	