



VOLVO XC60: 1LNS553

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------------------|
| Vinnumber: | YV1DZARCDG2852274 | Versionname: | 2.0 D3 2WD GEARTRONIC SUMMUM |
| First Registrationdate: | 30/10/2015 | Fiscalpower: | |
| Expertise Mileage: | 199850 | Power Kw: | 110 |
| Bodytype: | SUV | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | 4 Weel | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3814 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Luggage cover |
| GPS storage | Rear parking sensors |
| GPS storage | HD |
| Windows electric F | |
| Windows electric R | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Seats F heated | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|----------------------------|-------|----------------------------|
| | 235/55/19/101 V LightMetal | | | |
| Winter tyres: | Fr.L. | Continental: 4,5 mm | Fr.R. | Continental: 4,5 mm |
| | Re.L. | Dunlop: 6 mm | Re.R. | Dunlop: 6 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|--|----------------|
| Total cost ex VAT | 1407,43 |
| Floor covering F L, Burned, Smart repair | 64,32 |



| | |
|-----------------------------------|---------------|
| Door F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Interior, Smell, Ozone treatment | 152,58 |



Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 100,00



Sill outer R, Damaged, LI - Repair and paint (complete) 372,60



Seat cover F L, Worn, Acceptable 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 348,09



Wing R R, Chemical polution, LI - Repair and paint (complete) 369,84



Wing F L, Bump(s), Acceptable 0,00

No pictures to display