



VOLVO V60: 1ERW884			
Vinnumber:	YV1FW31A1D1130699	Versionname:	V60 D3 Kinetic St/St 136PK
First Registrationdate:	5/03/2013	Fiscalpower:	
Expertise Mileage:	83708	Power Kw:	100
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1608
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	215/55/16/97 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1490,23
Ignition key, Missing, E - Replace			150,00
<i>No pictures to display</i>			
Bumper R, Scratch(es), LI - Repair and paint (complete)			211,80



Bonnet, Chemical polution, LI - Repair and paint (complete)			290,08
---	--	--	---------------



Wing R R, Bad repair, Paint	0,00
-----------------------------	------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Wing F R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Wing R L, Chemical polution, LI - Repair and paint (complete)	308,20
---	--------

