



VOLVO V70: 1EDZ057

Vinnnumber:	YV1BW84ABD1260994	Versionname:	V70 D2 Kinetic St/St Powersh.115PK Aut.
First Registrationdate:	5/11/2012	Fiscalpower:	
Expertise Mileage:	173748	Power Kw:	85
Bodytype:	Break	Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3619
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 H LightMetal			
Winter tyres:	Fr.L.	Kleber: 6 mm	Fr.R.	Kleber: 6 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1213,92
Tailgate, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Windscreen, Stone chip(s), Acceptable			0,00
<i>No pictures to display</i>			
Door R L, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)			115,56



Roof, Chemical polution, LI - Repair and paint (complete) 577,80



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door panel F L, Scratch(es), Acceptable 0,00

No pictures to display


Boot carpet, Dirty, Cleaning 25,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Rear spoiler, Chemical polution, LI - Repair and paint (complete) 115,56



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00

