




BMW X1: 1DGY926			
Vinnumber:	WBAVN11000VU53918	Versionname:	X1 sDrive18 136PK
First Registrationdate:	14/05/2012	Fiscalpower:	
Expertise Mileage:	98876	Power Kw:	100
Bodytype:	SUV	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1513
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		


























Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/17/94 H LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1665,06
Bonnet, Chemical polution, LI - Repair and paint (complete)			290,08



		
Front bumper, Scratch(es), LI - Repair and paint (complete)		211,80
		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)		115,56
		
Roof, Chemical pollution, LI - Repair and paint (complete)		481,50
		
		
Roof pillar R, Bump(s), It - Spot repair		115,56
		
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Interior, Dirty, Cleaning		50,00
		
		
Alloy rim F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Front bumper, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56

