



| AUDI A5: XD9961         |                         |              |                                |
|-------------------------|-------------------------|--------------|--------------------------------|
| Vinnumber:              | <b>WAUZZ8T2FA025255</b> | Versionname: | <b>A5 SB DPF Quattro 177PK</b> |
| First Registrationdate: | <b>21/10/2014</b>       | Fiscalpower: |                                |
| Expertise Mileage:      | <b>199660</b>           | Power Kw:    | <b>130</b>                     |
| Bodytype:               | <b>Hatchback</b>        | Body color:  | <b>Black</b>                   |
| Gearbox:                | <b>MAN 6 VIT</b>        | Paint type:  | <b>Metalic</b>                 |
| Transmission:           | <b>Front</b>            | Rims summer: | <b>Aluminium</b>               |
| Fueltype:               | <b>Diesel</b>           | Oil level:   | <b>OK</b>                      |
| Battery functioning:    | <b>Yes</b>              | Parking lot: | <b>4306</b>                    |
| Number of doors:        | <b>4</b>                |              |                                |
| Number of seats:        | <b>4</b>                |              |                                |
| Number head rests:      | <b>4</b>                |              |                                |
| Rims summer:            | <b>Aluminium</b>        |              |                                |
| Category:               | <b>Passenger Car</b>    |              |                                |
| Oil level:              | <b>OK</b>               |              |                                |

| Options                        |                                 |
|--------------------------------|---------------------------------|
| Radio CD                       | Central consol F                |
| GPS storage                    | <b>HD</b> Front parking sensors |
| GPS storage                    | Rear parking sensors            |
| Windows electric F             |                                 |
| Windows electric R             |                                 |
| Cruise Control                 |                                 |
| Steering wheel multifunctional |                                 |
| Seats F heated                 |                                 |
| Type of headlighting           | <b>Headlighting Xenon</b>       |
| Type of GPS                    | <b>GPS big screen color</b>     |
| Type of Lining                 | <b>Lining leather</b>           |
| Type of climate control        | <b>Autom climate control</b>    |
| Sport seats                    |                                 |






| Limited Technical Inspection |           |                     |            |
|------------------------------|-----------|---------------------|------------|
| Airco functioning            | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile           | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime          | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                 | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                    | <b>OK</b> | Transmission        | <b>OK</b>  |
|                              |           | Lighting            | <b>OK</b>  |
|                              |           | Wiperblades         | <b>OK</b>  |

| Degree of wear |                                  |                       |       |                       |
|----------------|----------------------------------|-----------------------|-------|-----------------------|
| Winter tyres:  | <b>245/40/18/97 V LightMetal</b> |                       |       |                       |
|                | Fr.L.                            | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|                | Re.L.                            | <b>Michelin: 8 mm</b> | Re.R. | <b>Michelin: 8 mm</b> |

| Assistance equipment   |            |            |            |
|--|------------|------------|------------|
| Repair kit   | <b>Yes</b> | Compressor | <b>Yes</b> |
| Total cost ex VAT  |            |            | 1383,98    |
| Bumper R, Scratch(es), Acceptable                            |            |            | 0,00       |
| <i>No pictures to display</i>                                |            |            |            |
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) |            |            | 95,00      |



|                                   |  |  |      |
|-----------------------------------|--|--|------|
| Wing R R, Scratch(es), Acceptable |  |  | 0,00 |
| <i>No pictures to display</i>     |  |  |      |
| Windscreen, Repaired, Acceptable  |  |  | 0,00 |
| <i>No pictures to display</i>     |  |  |      |

|   |        |
|---|--------|
| Roof, Chemical pollution, LI - Repair and paint (complete)                          | 577,80 |
|    |        |
| Bonnet, Scratch(es), Acceptable   | 0,00   |
| No pictures to display  |        |
| Alloy rim R R, Scratch(es), Acceptable  | 0,00   |
| No pictures to display  |        |
| Alloy rim F R, Scratch(es), Acceptable  | 0,00   |
| No pictures to display  |        |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete)                        | 95,00  |
|    |        |
| Door frame F L, Scratch(es), Acceptable   | 0,00   |
| No pictures to display  |        |
| Wing R L, Scratch(es), Acceptable   | 0,00   |
| No pictures to display  |        |
| Tailgate, Scratch(es), LI - Repair and paint (complete)                             | 362,02 |
|   |        |
| Seat cover F L, Worn, Acceptable  | 0,00   |
|  |        |
| Front bumper, Scratch(es), LI - Repair and paint (complete)                         | 254,16 |
|  |        |
| Door R R, Scratch(es), Acceptable   | 0,00   |
| No pictures to display  |        |