



AUDI A6: 1FRV030			
Vinnumber:	<b>WAUZZZ4G7EN053570</b>	Versionname:	<b>A6 AVANT 163PK</b>
First Registrationdate:	<b>4/10/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>75874</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Break</b>	Body color:	<b>Light Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1215</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>NOT OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>225/60/16/98 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Dunlop: 4 mm</b>	Fr.R.	<b>Dunlop: 4 mm</b>
	Re.L.	<b>Dunlop: 5 mm</b>	Re.R.	<b>Dunlop: 5 mm</b>

Assistance equipment	
Repair kit	<b>Yes</b>
Compressor	<b>Yes</b>
Total cost ex VAT	3499,92
Bonnet, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper grille F R, Damaged, E - Replace	34,08



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Floor covering F L, Damaged, E - Replace

264,00



Door R L, Scratch(es), LI - Repair and paint (complete)

382,02



Interior, Dirty, Cleaning

150,00



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Rearview mirror glass R, Broken, E - Replace

21,60



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 369,84



Front bumper, Damaged, Le - Replace and paint 862,80



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Wing R L, Scratch(es), LI - Repair and paint (complete) 369,84



Bumper grille, Damaged, E - Replace 104,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

