



AUDI A5: 1EEW627

Vinnumber:	WAUZZZ8T7DA037107	Versionname:	SB TDie DPF 136PK
First Registrationdate:	12/11/2012	Fiscalpower:	
Expertise Mileage:	116532	Power Kw:	100
Bodytype:	Hatchback	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 3400 KM	Parking lot:	4727
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 H LightMetal			
Winter tyres:	Fr.L.	Firestone: 6 mm	Fr.R.	Firestone: 6 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment



















Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	3599,13
-------------------	---------

Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Ceiling, Damaged, Smart repair	64,32
--------------------------------	-------

		Door F L, Bump(s), PDR - Knock out without painting	63,00
		Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
		Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
		Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	0,00
		Tailgate, Bump(s), LI - Repair and paint (complete)	458,02
		Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
		Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
		Bonnet, Scratch(es), LI - Repair and paint (complete)	348,09
		Bumper trim R, Scratch(es), It - Spot repair	115,56



Wing F R, Scratch(es), LI - Repair and paint (complete)

264,21



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Headlight R, Scratch(es), E - Replace

456,00



Roof, Scratch(es), Acceptable

0,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

465,84



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete)

360,21

