


**MERCEDES A: 1EWC201**

Vinnumber:	<b>WDD1760121J039497</b>	Versionname:	<b>A 180 CDI BE 109PK</b>
First Registrationdate:	<b>4/04/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>58601</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OVER 35 DAGEN</b>	Parking lot:	<b>3721</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>1</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>SD</b>	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining semi-artificial leather</b>	
Type of climate control	<b>Manual climate control</b>	
Sport seats		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/45/17/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Kleber: 5 mm</b>	Fr.R.	<b>Kleber: 5 mm</b>
	Re.L.	<b>Kleber: 7 mm</b>	Re.R.	<b>Kleber: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>158,00</b>
-------------------	---------------

Bumper R, Repaired, P - Check	<b>0,00</b>
-------------------------------	-------------



Alloy rim R R, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

No pictures to display

Door R L, Repaired, P - Check	<b>0,00</b>
-------------------------------	-------------



Roof, Repaired, P - Check 0,00



Roof pillar L, Repaired, P - Check 0,00



Door F L, Repaired, P - Check 0,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Rear bulkhead lining, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Repaired, P - Check 0,00




Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror basis L, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, P - Check 0,00



Outer backrest protection L, Stain, Acceptable 0,00



Wing R L, Repaired, P - Check 0,00



Wing R R, Repaired, P - Check 0,00



Outer backrest protection R, Stain, Acceptable 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof pillar R, Repaired, P - Check 0,00



Tailgate, Bump(s), PDR - Knock out without painting 63,00



Bonnet, Repaired, P - Check 0,00



Door F R, Repaired, P - Check 0,00



Door R R, Repaired, P - Check 0,00

