



OPEL Zafira: 1HAP476

Vinnumber:	WOLPE9E35E2084981	Versionname:	ZAFIRA TOURER ecoFL.Cosmo S/S 136PK
First Registrationdate:	4/06/2014	Fiscalpower:	
Expertise Mileage:	134693	Power Kw:	100
Bodytype:	MPV	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3304
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Type of headlighting:	Headlighting Halogen
Type of Lining:	Lining leather

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 1394,50











Interior, Smell, Ozone treatment 152,58



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof pillar R, Scratch(es), It - Spot repair 115,56

	Bonnet, Chemical pollution, LI - Repair and paint (complete)	290,08
	Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	Glove compartment lid, Deformed, P - Check	0,00
	Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
	Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Trunk lid covering R, Scratch(es), Smart repair	110,64
	Sill trim F L, Scratch(es), Acceptable	0,00
	Door panel F L, Damaged, Smart repair	110,64
	Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>		