



#### **OPEL Insignia: 1HLY913**

Vinnnumber:	<b>W0LGM8GR4E1159559</b>	Versionname:	<b>INSIGNIA BRE ecoFLEX</b>
First Registrationdate:	<b>25/08/2014</b>	Fiscalpower:	<b>Edition 120PK</b>
Expertise Mileage:	<b>182272</b>	Power Kw:	<b>88</b>
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>2821</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

#### **Options**

Radio CD		Seats electric F L
GPS storage	<b>HD</b>	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	
Adaptive cruise control		

#### **Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

#### **Degree of wear**

	<b>225/55/17/101 V Steel</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>



























#### **Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT		<b>2770,68</b>	
Front bumper, Scratch(es), LI - Repair and paint (complete)		<b>211,80</b>	



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18

		
Ceiling, Hole, E - Replace		
494,00		
		
Windscreen, Stone chip(s), Windscreen repair		
0,00		
		
Bumper R, Scratch(es), LI - Repair and paint (complete)		
211,80		
		
Bonnet, Scratch(es), 67 - Polish		
55,19		
		
Tailgate, Bad repair, LI - Repair and paint (complete)		
301,68		
		
Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)		
318,35		
		
Wing F L, Scratch(es), LI - Repair and paint (complete)		
220,18		
		
Door R R, Scratch(es), LI - Repair and paint (complete)		
318,35		
		
Sidewall panel RR, Damaged, E - Replace		
70,80		
		
Wheel cover F R, Scratch(es), E - Replace		
30,00		



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)

318,35

