



**SKODA Octavia: 1FUF179**

Vinnumber:	<b>TMBJG9NE6E0077858</b>	Versionname:	<b>OCTAVIA COMBI Elegance</b>
First Registrationdate:	<b>25/10/2013</b>	Fiscalpower:	<b>105PK</b>
Expertise Mileage:	<b>176056</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Blue</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4733</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	<b>Headlighting Xenon</b>
Type of Lining	<b>Lining semi-leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 T LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 7,5 mm</b>	Fr.R.	<b>Goodyear: 7,5 mm</b>
	Re.L.	<b>Goodyear: 7,5 mm</b>	Re.R.	<b>Goodyear: 7,5 mm</b>


**Assistance equipment**

Total cost ex VAT	2799,96
Reflector, Broken, E - Replace	25,00





**Roof, Hail damage, PDR - Hail** 0,00





Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F R, Chemical polution, LI - Repair and paint (complete) 220,18



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Chemical polution, Acceptable 0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair 110,64



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door R R, Chemical polution, LI - Repair and paint (complete) 318,35



Ignition key, Missing, E - Replace 150,00




Wing F L, Chemical polution, LI - Repair and paint (complete) 220,18



Door trim R R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display



Door F R, Bad repair, Paint 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door R L, Chemical polution, Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Outer door handle R R, Scratch(es), E - Replace 120,00



Door R L, Scratch(es), Acceptable 0,00



Tyre repair kit, Missing, E - Replace 210,53

