



**BMW 3: 1GQF138**

Vinnumber:	<b>WBA3K11020F858804</b>	Versionname:	<b>3 TOURING 318dA 136PK Aut.</b>
First Registrationdate:	<b>1/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>55895</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1506</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining artificial leather</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/92 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

**Assistance equipment**

















Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

<b>Total cost ex VAT</b>	<b>1541,15</b>
--------------------------	----------------

<b>Bonnet, Bad repair, Paint</b>	<b>0,00</b>
----------------------------------	-------------



<b>Roof, Bump(s), Acceptable</b>	<b>0,00</b>
----------------------------------	-------------

No pictures to display		
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)		308,20
		
Door F R, Bump(s) and scratch(es), Acceptable		0,00
No pictures to display		
Wing R L, Bad repair, Paint		0,00
		
Door R R, Scratch(es), LI - Repair and paint (complete)		318,35
		
Front bumper, Scratch(es), LI - Repair and paint (complete)		211,80
		
		
Headlight L, Damaged, E - Replace		396,00
		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Bumper R, Scratch(es), LI - Repair and paint (complete)		211,80
