



HYUNDAI I40: 1ESH210

Vinnnumber:	KMHLB81UADU056012	Versionname:	i40 BRE Lounge ISG 115PK
First Registrationdate:	7/03/2013	Fiscalpower:	
Expertise Mileage:	153805	Power Kw:	85
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3603
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------


Total cost ex VAT	2504,07
-------------------	----------------

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	---------------





Luggage space cover, Damaged, Acceptable 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00




Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Rust, LI - Repair and paint (complete) 481,50



Door R R, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Interior, Dirty, Cleaning	50,00



Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
---	--------



Roof pillar R, Bump(s), LI - Repair and paint (complete)	220,18
--	--------



Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56

