


MERCEDES A: 1EWC184

Vinnumber:	WDD1760121J013119	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	4/04/2013	Fiscalpower:	
Expertise Mileage:	64052	Power Kw:	80
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 42 DAGEN	Parking lot:	3708
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining semi-artificial leather	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1240,24
-------------------	----------------

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------





Windscreen, Stone chip(s), Windscreen repair 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Repaired, P - Check 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 259,80



Wing R R, Repaired, P - Check 0,00



Seat F L compl, Worn, P - Check 0,00





Roof, Bump(s), Acceptable 0,00

No pictures to display

Door frame R R, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, P - Check 0,00



Door F L, Scratch(es), It - Spot repair 115,56



Seat cover F L, Stain, Cleaning 25,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Electricity circuit, Not functioning (well), P - Check 0,00



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper R, Repaired, P - Check 0,00



Rear bulkhead lining, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 414,35



Alloy rim F R, Damaged, Acceptable 0,00

No pictures to display

Seat cover F R, Stain, Cleaning 25,00



Tyre repair kit, Missing, E - Replace

210,53

