


**MERCEDES A: 1HJK341**

Vinnnumber:	<b>WDD1760121V027123</b>	Versionname:	<b>A 180 CDI BE 109PK</b>
First Registrationdate:	<b>1/08/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>162972</b>	Power Kw:	<b>80</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3711</b>
Maintenance:	<b>A3 OVER 1100KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>1</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	<b>SD</b> Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining semi-artificial leather</b>
Type of climate control:	<b>Manual climate control</b>
Sport seats	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/94 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 6 mm</b>	Fr.R.	<b>Bridgestone: 6 mm</b>
	Re.L.	<b>Bridgestone: 8 mm</b>	Re.R.	<b>Bridgestone: 8 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>1326,86</b>
Door R R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Trunk lid covering R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Alloy rim F L, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Outer backrest protection R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Wing F L, Repaired, P - Check			<b>0,00</b>



Bumper R, Bad repair, P - Check 0,00



Tailgate, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Dashboard, Scratch(es), Acceptable 0,00

No pictures to display

Outer backrest protection L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Luggage space cover, Damaged, Smart repair 110,64



Tires, Not original part, P - Check 0,00



Rear bulkhead lining, Scratch(es), E - Replace 44,95



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display








Door panel R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door frame F L, Scratch(es), Acceptable 0,00

<i>No pictures to display</i>		
Door frame R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Covering mid pillar L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Front bumper, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Bump(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Shutter / cover, Damaged, E - Replace		46,37
		
Bumper grille F R, Unclassped, N - Mount/Dismount		0,00
		
Covering mid pillar R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R R, Damaged, LI - Repair and paint (complete)		356,20
		
Internal Boot Lining R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Scratch(es), It - Spot repair		115,56
		
		
Ceiling, Damaged, Smart repair		64,32
		
Sill outer R, Scratch(es), LI - Repair and paint (complete)		334,50
		
Seat cover R L, Burned, Smart repair		64,32



Door panel F R, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Internal Boot Lining L, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Door frame R L, Bump(s) and scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

