


MERCEDES CLA: 1FXT838

| | | | |
|-----------------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber: | WDD1173011N059164 | Versionname: | CLA BER 200 CDI 136PK |
| First Registrationdate: | 2/12/2013 | Fiscalpower: | |
| Expertise Mileage: | 96514 | Power Kw: | 100 |
| Bodytype: | | Body color | Black |
| Gearbox: | MAN 6 VIT | Paint type | Metalic |
| Transmission: | Front | Rims summer | Aluminium |
| Fueltype: | Diesel | Oil level | OK |
| Battery functioning | Yes | Parking lot | 2223 |
| Number of doors | 4 | | |
| Number of seats | 5 | | |
| Number head rests | 1 | | |
| Rims summer | Aluminium | | |
| Category | Passenger Car | | |
| Oil level | OK | | |
| Registration Certificate Car (BE) | Yes | | |

Options

| | |
|--------------------------------|-----------------------------|
| Radio CD | Central consol F |
| GPS storage | Luggage cover |
| GPS storage | HD |
| Windows electric F | |
| Windows electric R | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining semi-leather |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 205/55/16/91 H LightMetal | | | |
| Summer tyres: | Fr.L. | Continental: 6 mm | Fr.R. | Continental: 6 mm |
| | Re.L. | Continental: 6 mm | Re.R. | Continental: 6 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|---|--------|
| Total cost ex VAT | 838,35 |
| Door R R, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) | 318,35 |



| | |
|---|--------|
| Windscreen, Repaired, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Rearview mirror housing R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) | 308,20 |



| | |
|---|------|
| Door F L, Bump(s) and scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display

| | |
|--|------|
| Bumper corner R R, Scratch(es), Acceptable | 0,00 |
|--|------|

No pictures to display

| | |
|---|--------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



| | |
|---------------------------|------|
| Roof, Bump(s), Acceptable | 0,00 |
|---------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display