



OPEL Astra: 1DST142

Vinnnumber:	WOLPD8EAXC8102736	Versionname:	ASTRA BRE ecoFLEX Enjoy
First Registrationdate:	14/08/2012	Fiscalpower:	150Ys DPF 95PK
Expertise Mileage:	175295	Power Kw:	70
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3532
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover	
Windows electric F	Rear parking sensors	
Cruise Control	Type of Tow bar	Tow bar fixed
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H Steel			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			2241,48
Seat cover F L, Stain, Acceptable			0,00



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35

	Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
	Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	Wheel cover R R, Scratch(es), E - Replace	30,00
	Wheel cover R R, Scratch(es), E - Replace	30,00
	Wheel cover R R, Scratch(es), E - Replace	30,00
	Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
	Door panel F L, Scratch(es), Acceptable	0,00
	Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
	Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
	Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
	Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>		
	Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
<i>No pictures to display</i>		
	Door panel F R, Scratch(es), Acceptable	0,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), E - Replace 30,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover R L, Stain, Acceptable 0,00



Wheel cover F L, Scratch(es), E - Replace 30,00



Rear spoiler, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner F L, Bump(s), LI - Repair and paint (complete) 115,56



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



