



VOLKSWAGEN Golf: DA0376

Vinnumber:	WVWZZZAUZEP077374	Versionname:	GOLF BER Highline DSG 150PK Aut.
First Registrationdate:	4/04/2014	Fiscalpower:	
Expertise Mileage:	124840	Power Kw:	110
Bodytype:	Hatchback	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2224
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	225/40/18/92 V LightMetal			
Winter tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	3299,64
-------------------	---------

Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Damaged, E - Replace 415,20



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Rearlight R tailgate, Scratch(es), 67 - Polish 55,19



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00


























Door R L, Chemical polution, LI - Repair and paint (complete) 318,35



Rearlight L tailgate, Scratch(es), 67 - Polish 55,19



Rearlight L, Scratch(es), 67 - Polish 55,19

		
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)		115,56
		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)		318,35
		
Door F R, Bump(s), PDR - Knock out without painting		63,00
		
Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)		301,68
		
Tyre F R, Damaged, E - Replace		132,00
		
Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)		318,35
		
		
Wing F L, Scratch(es), Acceptable		0,00

No pictures to display