



**BMW 3: 1GGL339**

Vinnumber:	<b>WBA3D11000F328728</b>	Versionname:	<b>3 BER 318d 136PK</b>
First Registrationdate:	<b>3/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>131418</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Berline</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1212</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Rear parking sensors
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/15/92 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Goodyear: 4 mm</b>	Fr.R.	<b>Goodyear: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**









Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT 2851,46

Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00


	Headlight L, Scratch(es), 67 - Polish	55,19
	Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
	Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
	Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	Wing R R, Bump(s), PDR - Knock out without painting	63,00
<i>No pictures to display</i>		
	Roof, Hail damage, PDR - Hail	300,00
	Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
	Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
Ignition key, Missing, E - Replace		150,00



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Bump(s), PDR - Knock out without painting 82,80



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Roof rail R, Bump(s), E - Replace 75,00



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Sill outer R, Deformed, P - Check 0,00



Door F L, Bump(s), PDR - Knock out without painting 63,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

No pictures to display

Door R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper moulding F M, Broken, E - Replace 20,00

