



**RENAULT Grand Espace: 1GHS481**

|                                    |                          |              |                                |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnnumber:                        | <b>VF1JKFJC650374121</b> | Versionname: | <b>GR.ESPACE Celsium 149PK</b> |
| First Registrationdate:            | <b>11/02/2014</b>        | Fiscalpower: |                                |
| Expertise Mileage:                 | <b>76060</b>             | Power Kw:    | <b>110</b>                     |
| Bodytype:                          | <b>MPV</b>               | Body color:  | <b>Beige</b>                   |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                 |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>               |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                      |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>3628</b>                    |
| Number of doors:                   | <b>5</b>                 |              |                                |
| Number of seats:                   | <b>7</b>                 |              |                                |
| Number head rests:                 | <b>7</b>                 |              |                                |
| Rims summer:                       | <b>Aluminium</b>         |              |                                |
| Category:                          | <b>Passenger Car</b>     |              |                                |
| Oil level:                         | <b>OK</b>                |              |                                |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Rear parking sensors         |
| Windows electric R             |                              |
| Cruise Control                 |                              |
| Steering wheel multifunctional |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining semi-leather</b>   |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |               |
|---------------------|-----------|---------------------|---------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b>    |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b>    |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>     |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>     |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>     |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>     |
|                     |           | Lighting            | <b>NOT OK</b> |
|                     |           | Wiperblades         | <b>OK</b>     |

**Degree of wear**

|               |                                   |                          |       |                          |
|---------------|-----------------------------------|--------------------------|-------|--------------------------|
|               | <b>225/55/17/101 V LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                             | <b>Michelin: 5 mm</b>    | Fr.R. | <b>Michelin: 5 mm</b>    |
|               | Re.L.                             | <b>Bridgestone: 6 mm</b> | Re.R. | <b>Bridgestone: 6 mm</b> |

**Assistance equipment**

































|   |         |
|---|---------|
| Total cost ex VAT                                       | 2260,59 |
| Wing F R, Scratch(es), LI - Repair and paint (complete) | 0,00    |



|   |        |
|---|--------|
| Door R R, Scratch(es), LI - Repair and paint (complete) | 382,02 |
|---|--------|



|   |        |
|---|--------|
| Door F L, Chemical polution, LI - Repair and paint (complete) | 382,02 |
|---|--------|

|   |  |   |   |        |
|---|--|---|---|--------|
|     |      |      | Alloy rim R R, Scratch(es), Acceptable                              | 0,00   |
| <i>No pictures to display</i>   |  |   |   |        |
|    |  |   | Door F R, Scratch(es), LI - Repair and paint (complete)             | 382,02 |
|    |    |    | Roof, Chemical polution, LI - Repair and paint (complete)           | 0,00   |
|    |     |     | Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) | 369,84 |
|    |     |     | Door moulding Lower R R, Scratch(es), Smart repair                  | 110,64 |
|   |    |    | Alloy rim F L, Scratch(es), Acceptable                              | 0,00   |
| <i>No pictures to display</i>   |  |   |   |        |
|  |  |   | Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 369,84 |
|  |  |  | Wing F L, Chemical polution, LI - Repair and paint (complete)       | 264,21 |
|  |   |   |   |        |
|  |   |   |   |        |
|  |   |   |   |        |
|  |   |   |   |        |