



SKODA OCTAVIA COMBI: BB8969

Vinnnumber:	TMBJG7NE9F0171044	Versionname:	1.6 CRTDI 77KW GREENTEC AMBITION
First Registrationdate:	16/02/2015	Fiscalpower:	
Expertise Mileage:	155512	Power Kw:	77
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2412
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H Steel				
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	No	Compressor	Yes
------------	-----------	------------	------------

Total cost ex VAT	480,44
-------------------	--------




Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Engine protective plate, Tear, E - Replace	35,00
--	-------



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing R L, Bump(s), PDR - Knock out without painting	63,00
---	-------



Wheel cover F R, Missing, E - Replace	30,00
---------------------------------------	-------



Wheel cover R L, Missing, E - Replace	30,00
---------------------------------------	-------



Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Rear bulkhead lining, Scratch(es), Smart repair	110,64
---	--------

