



ALFA ROMEO Giulietta: 1EVN528

Vinnnumber:	ZAR94000007223858	Versionname:	GIULIETTA BER Progress.Start&Stop
First Registrationdate:	1/04/2013	Fiscalpower:	105PK
Expertise Mileage:	114596	Power Kw:	77
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2116
Number of doors	5		
Number of seats	4		
Number head rests	4		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Luggage cover	
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/98 MS Steel			
Winter tyres:	Fr.L.	Kleber: 6 mm	Fr.R.	Kleber: 6 mm
	Re.L.	Kleber: 6 mm	Re.R.	Kleber: 6 mm

Assistance equipment

Repair kit	No	Compressor	No
------------	-----------	------------	-----------

Total cost ex VAT	461,36
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), E - Replace	30,00



Bumper R, Bad repair, Acceptable	0,00
----------------------------------	-------------



Wheel cover F L, Damaged, E - Replace 30,00



Wing F L, Bump(s), PDR - Knock out without painting 63,00



Compressor, Missing, E - Replace 0,00



Steel rim F R, Damaged, E - Replace 88,80



Front bumper, Bad repair, Acceptable 0,00



Floor covering F L, Damaged, E - Replace 72,00



Bumper R, Scratch(es), It - Spot repair 115,56



Internal Boot Lining L, Damaged, E - Replace 62,00



Wing F L, Bad repair, Acceptable 0,00

