


BMW 3: 1GIP993

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnnumber: | WBA3Y110X0D376012 | Versionname: | 3 GRAN TURISMO 318dA |
| First Registrationdate: | 18/02/2014 | Fiscalpower: | 136PK Aut. |
| Expertise Mileage: | 164836 | Power Kw: | 100 |
| Bodytype: | Hatchback | Body color: | Dark Brown |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2501 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|----------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining artificial leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 225/55/17/97 H LightMetal | | | |
| Winter tyres: | Fr.L. | Goodyear: 5 mm | Fr.R. | Goodyear: 5 mm |
| | Re.L. | Goodyear: 4 mm | Re.R. | Goodyear: 4 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|---|--------|
| Total cost ex VAT | 889,80 |
| Front bumper, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Seat cover F L, Worn, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Damaged, Le - Replace and paint | 677,80 |





| | |
|---|------|
| Wing R R, Bump(s) and scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display

| | |
|---------------------------------------|-------|
| Protection plate M, Hole, E - Replace | 74,00 |
|---------------------------------------|-------|



| | |
|--------------------------------|--------|
| Foglight R, Crack, E - Replace | 138,00 |
|--------------------------------|--------|

