



OPEL Astra: 1FBP136

Vinnumber:	W0LPC6DA6D1102333	Versionname:	ASTRA BER ecoFLEX Essentia S&S 95PK
First Registrationdate:	16/05/2013	Fiscalpower:	
Expertise Mileage:	221025	Power Kw:	70
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1708
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Luggage cover	
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	215/60/16/99 V Steel			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1818,97
-------------------	----------------


Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	---------------



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	---------------




Rear window, Scratch(es), E - Replace 0,00



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Interior, Dirty, Cleaning 100,00



Door F R, Bump(s) and scratch(es), Le - Replace and paint 0,00



Door R R, Bump(s) and scratch(es), Le - Replace and paint 0,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Roof pillar R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68

