



ISUZU D-max: 1EUE144

Vinnnumber:	MPATFS86JCT110665	Versionname:	D-MAX DOUBLE CAB 4WD LSX 163PK
First Registrationdate:	21/03/2013	Fiscalpower:	
Expertise Mileage:	211440	Power Kw:	120
Bodytype:	Off-road	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3225
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Type of Tow bar	Tow bar fixed
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	255/65/17/114 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Total cost ex VAT	2124,00
Front bumper, Bad repair, P - Check	0,00



Front bumper, Scratch(es), LI - Repair and paint (complete)	158,85
---	--------





Wing R R, Scratch(es), LI - Repair and paint (complete) 231,15



Interior, Dirty, Acceptable 0,00



Dashboard, Hole, Smart repair 110,64



Wing R L, Scratch(es), LI - Repair and paint (complete) 231,15



Glove compartment lid, Missing, E - Replace 228,00



Door R R, Bump(s), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 165,13



Seat cover F L, Worn, P - Check 0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 158,85





Interior, Smell, Ozone treatment 152,58



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 165,13



Seat belt R R, Tear, E - Replace 160,50

