



**PEUGEOT 3008: 1DGO171**

Vinnnumber:	<b>VF30U9HR8CS096641</b>	Versionname:	<b>3008 e-HDi Premium FAP BMP 112PK Aut.</b>
First Registrationdate:	<b>10/05/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>150082</b>	Power Kw:	<b>82</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1325</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric R			
Cruise Control			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/50/17 98 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 5 mm</b>	Fr.R.	<b>Uniroyal: 5 mm</b>
	Re.L.	<b>Uniroyal: 4 mm</b>	Re.R.	<b>Uniroyal: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>702,55</b>
-------------------	---------------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--------------------------------------------------------------	--------------



Wing R R, Bad repair, P - Check	<b>0,00</b>
---------------------------------	-------------



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>318,35</b>
---------------------------------------------------------------------	---------------



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), It - Spot repair 115,56



Door R L, Scratch(es), Acceptable 0,00

No pictures to display


Door panel R L, Scratch(es), Acceptable 0,00



Roof pillar L, Scratch(es), Acceptable 0,00

No pictures to display


Bumper grille F L, Scratch(es), Smart repair 110,64



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Backrest cover F R, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Bump(s), PDR - Knock out without painting 63,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display