



SKODA Octavia: 1GIQ642

Vinnnumber:	TMBJG7NEXE0129013	Versionname:	OCTAVIA COMBI
First Registrationdate:	18/02/2014	Fiscalpower:	GreenLine Ambition 110PK
Expertise Mileage:	149190	Power Kw:	81
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3505
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 1 mm	Fr.R.	Michelin: 1 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1926,88
Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	290,08




Wing R L, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display


Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35




Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Bad repair, Paint 0,00

