



VOLKSWAGEN Golf: 1H2C294

Vinnnumber:	WVWZZZAUZFP037856	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	4/11/2014	Fiscalpower:	
Expertise Mileage:	91491	Power Kw:	77
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance	23700	Parking lot:	2426
Maintenance	OK		
Maintenance	308 DAGEN		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	SD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 8 mm	Re.R.	Continental: 8 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	264,03
Tailgate, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Dashboard, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof pillar L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tires, Not original part, P - Check	0,00



Door panel F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Ceiling, Stain, P - Check	0,00



Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Scratch(es), 67 - Polish	55,19



Bumper R, Repaired, P - Check	0,00
-------------------------------	------



Armrest F Mid, Stain, P - Check	0,00
---------------------------------	------



Internal Boot Lining R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Internal Boot Lining L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Bad repair, P - Check	0,00



Door panel R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), E - Replace	73,40





Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Floor covering F L, Burned, Acceptable 0,00

No pictures to display

Door F L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Centre console, Scratch(es), Smart repair 110,64



Rear bulkhead lining, Scratch(es), Acceptable 0,00

No pictures to display

Shutter / cover, Missing, E - Replace 24,80



Rear window, Not original part, Remove lettering 0,00



Sill trim R L, Scratch(es), Acceptable 0,00

No pictures to display