


MERCEDES A: 1GTF465

Vinnnumber:	WDD1760081V015562	Versionname:	A 200 CDI 136PK
First Registrationdate:	23/04/2014	Fiscalpower:	
Expertise Mileage:	156426	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4409
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Sun Roof electric
GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 V LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment















Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1020,00
-------------------	----------------

Backrest cover F L, Scratch(es), Acceptable	0,00
---	-------------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------

			Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
			Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
			Bumper corner R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
Door panel F L, Deformed, P - Check				0,00
			Front bumper, Accident, Le - Replace and paint	735,00
			Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
Door R R, Scratch(es), Acceptable				0,00
<i>No pictures to display</i>				
Door R L, Bump(s), Acceptable				0,00
<i>No pictures to display</i>				