



HYUNDAI i20: 1EUG830

Vinnnumber:	NLHBB51RADZ199443	Versionname:	i20 BER Lounge 90PK
First Registrationdate:	22/03/2013	Fiscalpower:	
Expertise Mileage:	75098	Power Kw:	66
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4820
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover
Windows electric F	Type of Tow bar
Cruise Control	Tow bar removable
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/84 H LightMetal			
Summer tyres:	Fr.L.	Semperit: 6 mm	Fr.R.	Semperit: 6 mm
	Re.L.	Semperit: 5 mm	Re.R.	Semperit: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2412,18
Interior, Stain, Cleaning	100,00





Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Internal Boot Lining L, Scratch(es), Acceptable 0,00

No pictures to display


Door R L, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Rust, LI - Repair and paint (complete) 481,20



Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Rust, LI - Repair and paint (complete) 232,06



Rearview mirror housing L, Difference in color, Acceptable 0,00

No pictures to display

Front bumper, Accident, Le - Replace and paint 607,20



Wing R R, Bump(s), LI - Repair and paint (complete) 342,56



Rearview mirror R complete, Damaged, Le - Replace and paint 259,00




Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44





Bumper grille, Accident, E - Replace	30,72
--------------------------------------	-------



Internal Boot Lining R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing F R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Steering wheel, Dirty, Acceptable	0,00
-----------------------------------	------

No pictures to display