



AUDI A1: 1FJC030

Vinnnumber:	WAUZZZ8X1DB096540	Versionname:	A1 5B Attraction 90PK
First Registrationdate:	12/07/2013	Fiscalpower:	
Expertise Mileage:	131608	Power Kw:	66
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance	26900	Parking lot:	2109
Maintenance	OK		
Maintenance	698 DAGEN		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/88 T Steel			
Winter tyres:	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Fulda: 2 mm	Re.R.	Fulda: 2 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	825,00
Tailgate, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Outer door handle F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Bad repair, P - Check	0,00



Sill trim R L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bump(s), PDR - Knock out without painting 63,00



Door F L, Scratch(es), It - Spot repair 115,56



Sill trim R R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Door F L, Repaired, P - Check 0,00



Wheel cover R L, Scratch(es), E - Replace 24,00



Door F R, Bad repair, P - Check 0,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Bad repair, P - Check 0,00



Rear bulkhead lining, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bad repair, P - Check 0,00



Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Tires, Not original part, P - Check 0,00



Wheel cover F L, Scratch(es), E - Replace 24,00



Dashboard, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 217,44




Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper R, Damaged, LI - Repair and paint (complete) 217,44





Wheel cover R R, Scratch(es), E - Replace	24,00
---	-------



Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Wing R R, Bad repair, P - Check	0,00
---------------------------------	------



Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wheel cover F R, Scratch(es), E - Replace	24,00
---	-------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display