



<b>OPEL Astra: 1EPB884</b>			
Vinnnumber:	<b>WOLPD8EA2D8035003</b>	Versionname:	<b>ASTRA BRE ecoFLEX Enjoy St/St 95PK</b>
First Registrationdate:	<b>12/02/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>156643</b>	Power Kw:	<b>70</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3728</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>			
Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>Tow bar fixed</b>
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>215/60/16/9 H Steel</b>			
Winter tyres:	Fr.L.	<b>Fulda: 8 mm</b>	Fr.R.	<b>Fulda: 8 mm</b>
	Re.L.	<b>Fulda: 9 mm</b>	Re.R.	<b>Fulda: 9 mm</b>

<b>Assistance equipment</b>			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>774,60</b>
<b>Dashboard, Scratch(es), Acceptable</b>			<b>0,00</b>



<b>Wheel cover R R, Scratch(es), E - Replace</b>	<b>30,00</b>
--	--------------



<b>Bumper R, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------

<i>No pictures to display</i>	
<b>Central pillar L, Bump(s), It - Spot repair</b>	<b>115,56</b>

			Headlight L, Scratch(es), P - Check	0,00
--	--	---	-------------------------------------	------

		Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)		301,68
---	---	---	--	--------

			Wing F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>					

Outer door handle F L, Scratch(es), LI - Repair and paint (complete)				115,56
--	--	--	--	--------



		Bumper spoiler F, Incomplete, P - Check		0,00
--	--	---	--	------

		Rearview mirror housing R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>				

Front bumper, Scratch(es), LI - Repair and paint (complete)				211,80
---	--	--	--	--------

			Wing R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>					

Door panel F L, Scratch(es), Acceptable				0,00
---	--	--	--	------

				
---	---	--	--	--