


SKODA Superb: 1EVQ985

Vinnumber:	TMBJE73T5D9045618	Versionname:	SUPERB COMBI Gtec Elegance DPF 140PK
First Registrationdate:	2/04/2013	Fiscalpower:	
Expertise Mileage:	73310	Power Kw:	103
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2323
Maintenance:	23/04/2018		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats R heated
GPS storage	HD	Seats electric F L
GPS storage		Seats electric F R
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1102,98

Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16




Roof, Stain, Acceptable 0,00



Interior, Dirty, Chemical cleaning 100,00




Bumper grille, Broken, E - Replace 34,08



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Boot carpet, Stain, Repair/replace (lump sum) 150,00






Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bump(s), PDR - Knock out without painting 63,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Interior, Smell, Ozone treatment	152,58
<i>No pictures to display</i>	
Maintenance, Maintenance, Execute	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	