


**SKODA Superb: 1EWX042**

Vinnumber:	<b>TMBJE73T9D9047792</b>	Versionname:	<b>SUPERB COMBI Ambition</b>
First Registrationdate:	<b>10/04/2013</b>	Fiscalpower:	<b>DPF DSG 140PK Aut.</b>
Expertise Mileage:	<b>140042</b>	Power Kw:	<b>103</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4807</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage	<b>HD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>Tow bar removable</b>
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Semperit: 5 mm</b>	Fr.R.	<b>Semperit: 5 mm</b>
	Re.L.	<b>Semperit: 5 mm</b>	Re.R.	<b>Semperit: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

**Total cost ex VAT** 1337,53


**Door F R, Bad repair, Paint** 0,00

**Wing R L, Repaired, Acceptable** 0,00

*No pictures to display*
**Wing F R, Bad repair, Paint** 0,00



Interior, Stain, Cleaning 100,00



Wing F L, Scratch(es), LI - Repair and paint (complete) 264,21



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16




Engine protective plate, Missing, E - Replace 85,00



Roof, Bump(s), Acceptable 0,00

No pictures to display

Bonnet, Bad repair, Paint 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Door F L, Bad repair, Paint 0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Bad repair, Paint 0,00



Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen, Damaged, E - Replace 0,00



Door R R, Bad repair, Paint 0,00



Wing R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

