



VOLKSWAGEN Touran: 1ELB222

| | | | |
|-------------------------|--------------------------|--------------|-----------------------------|
| Vinnumber: | WVGZZZ1TZDW062523 | Versionname: | TOURAN Trendline BMT |
| First Registrationdate: | 10/01/2013 | Fiscalpower: | Start/Stop 105PK |
| Expertise Mileage: | 152203 | Power Kw: | 77 |
| Bodytype: | Hatchback | Body color: | Dark Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4431 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | |
|--------------------------------|------------------------------|--------------------------|
| Radio CD | Sun Roof electric | |
| Windows electric F | Panoramic roof | |
| Windows electric R | Central consol F | |
| Cruise Control | Luggage cover | |
| Steering wheel multifunctional | Type of Tow bar | Tow bar removable |
| Radio multimedia | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/55/16/91 H LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 381,35 |
|-------------------|---------------|

| | |
|---|--------------|
| Tailgate, Bump(s), PDR - Knock out without painting | 63,00 |
|---|--------------|



| | |
|--|-------------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
|--|-------------|

No pictures to display

| | |
|-----------------------------------|-------------|
| Wing R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

| | |
|---------------------------------------|-------------|
| Front bumper, Scratch(es), Acceptable | 0,00 |
|---------------------------------------|-------------|

No pictures to display

| | |
|-----------------------------------|-------------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|-------------|

No pictures to display

| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-------------------------------|------|
| Door R L, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display

| | |
|---|--------|
| Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 318,35 |
|---|--------|



| | |
|-------------------------------|------|
| Wing F L, Bump(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display