



VOLVO V70: 1EQ177

Vinnumber:	YV18W88A1D1270225	Versionname:	V70 D4 Kinetic St/St
First Registrationdate:	21/02/2013	Fiscalpower:	163PK
Expertise Mileage:	201666	Power Kw:	120
Bodytype:	Break	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2510
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/16/95 V LightMetal			
Summer tyres:	Fr.L.	Firestone: 3 mm	Fr.R.	Firestone: 3 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1968,60
-------------------	---------

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Windscreen Damaged, F - Replace	0,00
---------------------------------	------

Windscreen, Damaged, L - Replace 0,00



Bonnet, Bad repair, Acceptable 0,00



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Front bumper, Scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 369,84



Wing F L, Scratch(es), LI - Repair and paint (complete) 264,21



Rocker panel inner R L, Scratch(es), Acceptable 0,00

No pictures to display

Floor covering F L, Hole, Smart repair 64,32



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16





Wing F R, Scratch(es), LI - Repair and paint (complete)	264,21
---	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display