



VOLVO V40: 1FAN373			
Vinnnumber:	YV1MV8481D2054396	Versionname:	V40 D2 Base 115PK
First Registrationdate:	7/05/2013	Fiscalpower:	
Expertise Mileage:	128428	Power Kw:	84
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2333
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
GPS storage	HD Luggage cover
GPS storage	Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK















Degree of wear				
	205/50/17/93 W LightMetal			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes

Total cost ex VAT	1241,90
Roof, Scratch(es), LI - Repair and paint (complete)	481,50



Door F R, Bump(s), Acceptable	0,00
--------------------------------------	-------------

No pictures to display		
Bonnet, Scratch(es), Acceptable		0,00
No pictures to display		
Tyre R L, Damaged, E - Replace		132,00
 		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
  		
		
Alloy rim R L, Scratch(es), E - Replace		235,20
  		
		
Wing R L, Bump(s), PDR - Knock out without painting		63,00
  		
		
Door F L, Chemical polution, Acceptable		0,00
No pictures to display		
Alloy rim R R, Scratch(es), E - Replace		235,20
