



**BMW 5: 1GAE637**

|                                    |                          |              |                                   |
|------------------------------------|--------------------------|--------------|-----------------------------------|
| Vinnumber:                         | <b>WBA5J11090D065331</b> | Versionname: | <b>5 TOURING 518dA 136PK Aut.</b> |
| First Registrationdate:            | <b>4/12/2013</b>         | Fiscalpower: |                                   |
| Expertise Mileage:                 | <b>136127</b>            | Power Kw:    | <b>100</b>                        |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Brown</b>                      |
| Gearbox:                           | <b>Automatic</b>         | Paint type:  | <b>Metalic</b>                    |
| Transmission:                      | <b>Back</b>              | Rims summer: | <b>Aluminium</b>                  |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                         |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2608</b>                       |
| Number of doors:                   | <b>5</b>                 |              |                                   |
| Number of seats:                   | <b>5</b>                 |              |                                   |
| Number head rests:                 | <b>5</b>                 |              |                                   |
| Rims summer:                       | <b>Aluminium</b>         |              |                                   |
| Category:                          | <b>Passenger Car</b>     |              |                                   |
| Oil level:                         | <b>OK</b>                |              |                                   |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                   |

**Options**

|                              |                              |                       |
|------------------------------|------------------------------|-----------------------|
| Radio CD                     |                              | Sun Roof electric     |
| GPS storage                  |                              | Central consol F      |
| GPS storage                  | <b>HD</b>                    | Luggage cover         |
| Windows electric F           |                              | Front parking sensors |
| Windows electric R           |                              | Rear parking sensors  |
| Cruise Control               |                              |                       |
| Steering wheel multifunction |                              |                       |
| Seats F heated               |                              |                       |
| Radio multimedia             |                              |                       |
| Type of headlighting         | <b>Headlighting Halogen</b>  |                       |
| Type of GPS                  | <b>GPS big screen color</b>  |                       |
| Type of Lining               | <b>Lining leather</b>        |                       |
| Type of climate control      | <b>Autom climate control</b> |                       |
| Level control                |                              |                       |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                   |                          |       |                          |
|---------------|-----------------------------------|--------------------------|-------|--------------------------|
|               | <b>225/55/17/101 V LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                             | <b>Goodyear: 6 mm</b>    | Fr.R. | <b>Goodyear: 6 mm</b>    |
|               | Re.L.                             | <b>Bridgestone: 6 mm</b> | Re.R. | <b>Bridgestone: 6 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>608,32</b> |
|-------------------|---------------|

|                                      |             |
|--------------------------------------|-------------|
| Rear window, Scratch(es), Acceptable | <b>0,00</b> |
|--------------------------------------|-------------|

*No pictures to display*

|                                   |             |
|-----------------------------------|-------------|
| Door R R, Scratch(es), Acceptable | <b>0,00</b> |
|-----------------------------------|-------------|

*No pictures to display*

|  |               |
|--|---------------|
| Alloy rim R L, Scratch(es), 1 - Repair | <b>100,00</b> |
|--|---------------|



Tailgate, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror basis L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Central pillar L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Door F L, Bump(s), Acceptable 0,00

No pictures to display