



<b>FORD C-MAX: 1AVN196</b>			
Vinnumber:	<b>WFOJXXWPBJBC70007</b>	Versionname:	<b>C-MAX Trend DPF 95PK</b>
First Registrationdate:	<b>1/04/2011</b>	Fiscalpower:	
Expertise Mileage:	<b>177381</b>	Power Kw:	<b>70</b>
Bodytype:	<b>Hatchback</b>	Body color	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Opaque</b>
Transmission:		Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3707</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

<b>Options</b>	
Radio CD	
Windows electric F	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>205/55/16/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 3 mm</b>	Fr.R.	<b>Goodyear: 0 mm</b>
	Re.L.	<b>Goodyear: 3 mm</b>	Re.R.	<b>Goodyear: 3 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>2350,03</b>
<b>Internal Boot Lining L, Damaged, E - Replace</b>			<b>69,00</b>



<b>Tailgate, Rust, LI - Repair and paint (complete)</b>	<b>301,68</b>
---	---------------



<b>Wing R L, Scratch(es), LI - Repair and paint (complete)</b>	<b>308,20</b>
--	---------------



Luggage space cover, Missing, E - Replace 50,00



Interior, Dirty, Forfeit 36,00



Door R R, Difference in color, Acceptable 0,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Wheel cover R R, Scratch(es), E - Replace 30,00



Protection plate M, Tear, E - Replace 62,00



Rear window, Scratch(es), E - Replace 370,00



Ceiling, Damaged, E - Replace 494,00





Internal Boot Lining R, Damaged, E - Replace 69,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover F R, Scratch(es), E - Replace 30,00

