



BMW 5: 1GNU641

Vinnnumber:	WBA5J11010D336012	Versionname:	5 TOURING 518d 136PK
First Registrationdate:	20/03/2014	Fiscalpower:	
Expertise Mileage:	108893	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3816
Maintenance:	25000 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage		Seats electric F R	
GPS storage	HD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunction		Type of Tow bar	Tow bar fixed
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment











Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 2433,27

Bonnet, Hail damage, PDR - Knock out without painting 0,00



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50

	Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	301,68
	Roof, Hail damage, PDR - Knock out without painting	0,00
	Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	404,20
	Rearview mirror housing R, Bad repair, LI - Repair and paint (complete)	115,56
	Wing R R, Bad repair, P - Check	0,00
	Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
	Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
	Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Wing F L, Bad repair, LI - Repair and paint (complete)	220,18
--	--------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

