



MERCEDES Sprinter 300: 1ABH296

Vinnnumber:	WDB9062351N462239	Versionname:	SPRINTER 313 CH2C LWB
First Registrationdate:	22/11/2010	Fiscalpower:	A3 129PK 3500kg
Expertise Mileage:	213321	Power Kw:	95
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	LCV17
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Type of Tow bar Tow bar fixed
Type of headlighting Headlighting Halogen	
Type of Lining Lining semi-artificial leather	

Limited Technical Inspection

Tires wear profile	OK	Battery functioning	Yes
Idle position	OK	Power steering	Yes
Engine startingtime	OK	Sound engine	OK
Exhaust gass	OK	Clutch test	OK
Handbrake	OK	Wiper fluid level	OK
		Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/16/115 R Steel			
Summer tyres:	Fr.L.	Michelin: 8 mm	Fr.R.	Michelin: 8 mm
	Re.L.	Bridgestone: 8 mm	Re.R.	Bridgestone: 8 mm

Assistance equipment

Total cost ex VAT	1630,58
Wheel arch cover F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Rust, Acceptable	0,00



Electricity circuit, Not original part, P - Check	0,00
---	------



Dashboard, Damaged, E - Replace	35,00
---------------------------------	-------



Foglight L, Broken, E - Replace

115,50



Door panel R L, Hole, E - Replace

91,50



Seat cover R R, Hole, Acceptable

0,00



Mirror side blinker R, Scratch(es), Acceptable

0,00



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper grille F R, Damaged, E - Replace

169,00



Door R R, Accident, Le - Replace and paint

746,18



Roof, Not original part, Acceptable

0,00

No pictures to display

Sill outer L, Rust, Acceptable

0,00

No pictures to display

Front bumper, Broken, E - Replace

398,40



Seat cover F L, Hole, Acceptable

0,00



Wheel arch cover R R, Broken, P - Check

0,00



Instrument panel complete, Hole, P - Check 0,00



Steering wheel, Worn, Acceptable 0,00



Interior, Dirty, Cleaning 75,00

